


00460" 8229960



JOIN FIG.1b Fig. 1a

JOIN FIG. 1a




Fig. 1b

SECRETARY OF DEFENSE




Fig. 2




Fig. 3




Fig. 4




Fig. 5




Fig. 6

09662226-091400




Fig. 8




Fig. 9




Fig. 10




Fig. 11




Fig. 12




Fig. 13





Fig. 14






Fig. 16




Fig. 18

004760-2229950




Fig. 19




Fig. 20

004160-82229960




Fig. 21

004660-01400





Fig. 22






Fig. 24




Fig. 25




Fig. 26




Fig. 27

004160" 32229960




Fig. 28






Fig. 29

CONDITIONAL INSTRUCTION



CONVENTIONAL INSTRUCTION



SAVINGS: 3 CYCLES

Fig. 30

0966223-091400




Fig. 31

001160-3229960




Fig. 32




Fig. 33

004T60-8229960




Fig. 34




Fig. 35




Fig. 36

096222B - 09.14.00




Fig.37




Fig. 38




Fig. 39

0041400-82229960




Fig. 40




Fig. 41




Fig. 42




Fig. 43

004160-8229360